Inspection Report					
PI#	18A02025	Item name	6A Battery charger	Item#	BTC-110A
Qty	6PCS*100CTN=600PCS	Checked Qty	5 CTN= 30 PCS	Date	2018/9/15
Inspection Method	AQL	Inspection level	AQL II	Inspector	Eric

Mass Goods





PASS

1. Package

Inspection Program	Inspection record		CR	MJ	MI
mopeodon r rogram	mopositori record		Ac/Re	Ac/Re	Ac/Re
Shipping marks	DI CHARGER PRO BYC-11 GA BYC-11 GA G.W.: 17,5 kg Sizes: 0.69 kg 26 kg 26 kg 32 m Quantity: 6 pcs. Carlon No: [g +100]	PASS			
Gift box	DICHARGER PRO PINE PROTO	PASS			

Product label	D1 CHARGER PRO BTC-110A Quality & Inspection -Cooperated with good reputation suppliers, like trainibe full and so only -186% check space parts quality which produced from mutching suppliersOC checking each step from spare parts to production on the full of line CEG D X M B A A B B B B B	PASS	
Manual & Warranty Card	The second secon	PASS	
Carton Weight & Size	Size: 0.68*0.26*0.32m Weight: 7.4kg	PASS	

2. Product Appearance

Inspection Program	Inspection record		CR Ac/Re	MJ Ac/Re	MI Ac/Re
Whole set		PASS	ACRE	ACINE	AURE
Internal structure		PASS			

3. Key parts

Inspection Program	Inspection red	cord	-	CR	MJ	MI
Input line	71 tim	2201/	PASS	Ac/Re	Ac/Re	Ac/Re
Output line	7 0 0 1901 2 3 4 5	12V 1.9m	PASS			
Switch		YH2X 5A	PASS			

Transformer		Copper material	PASS			
-------------	--	-----------------	------	--	--	--

4. Product characters

Inspection Program	Inspection record	CR	MJ	MI
	A		Ac/Re	Ac/Re
Test of Short Circuit Protection	SV SAFETY ACLAN SA	ASS		
Test of Reverse Polarity Protection	P.	ASS		

6V/12V Charging Current	12.486U 4.1990 CC 27.130 4.2860 CC 27.13	PASS		
High Voltage Test 3750V		PASS		

J. DEIECIS & IIIDIOVEITEIT	5.	Defects	&	Improvemen ³
----------------------------	----	---------	---	-------------------------

Result

Defects record	improvement	improvement	
6. Inspection Result			

PASS